

1/6




FIG. 1

Moving dash line 19  
outward slightly

2/6




FIG. 2

Moving dotted line  
19 outward slightly.  
Eliminating outer dash line.

3/6




FIG. 3A






FIG. 3B

4/6



5/6




FIG. 6




FIG. 7A




FIG. 7B




FIG. 8

6/6




FIG. 9




FIG. 10

3/6





Fig 1  
 Slot 16 not shown




FIG. 4




FIG. 5






FIG. 6




FIG. 7A




FIG. 7B




FIG. 8

6/6




FIG. 9




FIG. 10